

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



## Figure 1




Figure 2a




Figure 2b




Figure 2c




Figure 2d




Figure 2e




Figure 2f




Figure 2g




Figure 2h




Figure 2i




Figure 2j




Figure 2k




Figure 2l




Figure 2m




Figure 2n




Figure 2o




Figure 2p




Figure 2q




Figure 2r




Figure 2s




Figure 2t




Figure 2u




Figure 3




Figure 4.  $R \cdot Q_g$  as a function of trench depth




Figure 5a. In-circuit efficiency comparison for the Control FET at 200kHz




Figure 5b. In-circuit efficiency comparison for the Control FET at 1Mhz




Figure 6a. In-circuit efficiency comparison for the Sync FET at 200kHz




Figure 6b. In-circuit efficiency comparison for the Sync FET at 750kHz